## Weekly coordinator report (3. -10. 8. 2018)

#### Jan Matoušek University and INFN Trieste

10. 8. 2018, CERN








#### Beam and accesses






Before the MD.

After the MD.

#### Beam

- Beam rather good (certainly better than last week!)
- Reasonably stable intensity  $\approx 120 \times 10^{11} \text{ p/s}$  on T6.
- Except few intensity spikes and the LHC-filling periods.

# Beam and accesses bend 03 -- 'access magnet'



Before the MD.

After the MD.

#### Accesses

- Fri 14:00 Access during no beam,
  - ECAL1 missing part fixed,
  - RICH LV fans: fuse returned.

Wed-Thu

Wed 7:00

- To restore DC HV (CAEN crate).
- Machine development.

Fri 18:00 RichWall sending almost no

#### **Detectors: Incidents**



#### In general, no major problems!

#### Fri 18:00


- RichWall sending almost no data.
  - 1.5 h access, not solved,
- after we took run 285023 without RW,
- finally 2 guilty ports found and excluded,
- fixed on Wednesday.


#### Monday

- ECAL1 src id 624 100 % errors
- LOAD  $\rightarrow$  no config server.
- pccofe23 needs restart, but that requires acces... → done on Wednesday.


#### Wed 7:00

- HV trip of DCs (or CAEN rebooted by itself),
- DC04 not recovered → access, powercycled CAEN.





RW Fri-Wed.



DC00 and 04 HV.


#### Detectors: Common troulbes



- LOAD of a detector ends in 'no config server' error.
  - if pccofeXX not reachable by ping (ping pccofeXX or check\_daq), it probably should be powercycled.
  - do not powercyce pccofe10 and 52!
  - If in doubt, call the expert or ask experienneed people around...
- PMMs give errors and/or have data missing
  - no errors, but missing data
    → stop & LOAD -ra.
  - error persists several spills → stop & LOAD -A,
  - I2C error → powercyce MM LV,
- However, please do not powercycle LV of random detectors if you are not sure about it!
- DSc, MWPCs missing cards or ports, usually cured by LOAD.

Watch the MTV and (be) coool!






#### Detectors: Common troulbes



- LOAD of a detector ends in 'no config server' error.
  - if pccofeXX not reachable by ping (ping pccofeXX or check\_daq), it probably should be powercycled.
  - do not powercyce pccofe10 and 52!
  - If in doubt, call the expert or ask experienneed people around...
- PMMs give errors and/or have data missing
  - no errors, but missing data
    → stop & LOAD -ra.
  - error persists several spills → stop & LOAD -A,
  - I2C error → powercyce MM LV,
- However, please do not powercycle LV of random detectors if you are not sure about it!
- DSc, MWPCs missing cards or ports, usually cured by LOAD.

Watch the MTV and (be) coool!








## Detectors: Persisting problems



DC04 missing part of plane,

DC05 time to time small % of erors that don't dissappear after LOAD. They are from periferal region and can be ignored.

CEDARs frontend electronics problems (noise?), not working at all.



#### Other things: Water leaks



- in the beam tunnel BMS06 cooling water,
- from the air-conditioning unit next to polarised target barracs.
- Both fixed on Wednesday by EN-CV (even if the tunnel was not their responsibility, but theresponsible was on holiday)



Water leak in the tunnel.



AC unit next to PT barracks.




A light below.


## Other things: MD and similar




- Target measured and reversed the polarisation
  - Polarising Wed 11:30–21:30, continued Thu 8:45–00:00
  - Reached +74% and -70%.
- RichWall 2 missig ports FE cards exchanged.
- ECAL1 pccofe23 restarted.
- ECAL2 changed HV bases.
- DAQ
  - cross-point switch installed to MUX03,
  - fast run start/stop procedure deployed.
- Wed 23:00–01:30 Veto tests
  - deadtime measurement at different beam intensities,
  - run with no veto applied to OT and MT.
- Thu 11:00 alignment runs
- Thu most of the day: trigger test runs with low intensity π beam taken while polarising.
- This way the tilme with long SC with 1 spill was effectively used!



## Spills collected





Integrated number of good physics spills collected.

			Pol.	Good DY spills		
W09:	Wed	1. 8. 00:00	- Wed	8. 8. 8:00		
Wed 00:00	_	Fri 11:00	-+	8928		
Fri 11:00	_	Sat 16:00	-+	4892		
Sat 16:00	_	Sun 16:00	-+	4258		
Sun 16:00	_	Mon 16:00	-+	3900		
Mon 16:00	_	Tue 16:00	-+	2934		
Tue 16:00	_	Wed 08:00	-+	2457		
Total in W09			-+	27369		
W10: Thu 9. 8. 00:00 - Wed 15. 8. 8:00						
Thu 00:00	_	Thu 16:00	+-	1270		
Thu 16:00	_	Fri 11:00	+-	1488		
So far in W10			+-	2758		




Thanks to all shifters and experts, good luck to Oleg!

## Backup: Friday 11:00 – Saturday 16:00



- 14:00 14:57 Access during no beam
  - ECAL1 missing part fixed,
  - PA11 prob. cable connection touched,
  - RICH LV fans: found off, unplugged and without fuse?
- 18:00 RichWall went missing in coool and MTV.
  - 1.5 access, not solved.
  - after we took run 285023 without RW
  - 2 guilty ports found and excluded (one card problem - easy fix if there is no beam for 1 h, and one to be looked at on MD)
- night: no DSC info from CEDARs (Christophe submitted a ticket, solved Mo 9:40).

DIP Manager						
Name	State	Heart beat	Action			
DIP 7	A	2018.08.04 03:50:58.552	Start Stop			



## Backup: Saturday 16:00 – Sunday 16:00



- MTV and coool not getting data several times.
  - solved by CleanDAQ,
  - to go to "turned off" state might have been sufficient.
- During the night: DC05 timeout on port, could not be reloaded. shift powercycled the pccofe, which should not be done, fortunately it was OK.

# Backup: Sunday 16:00 – Monday 16:00



 $\bullet$  Basically everything OK...



- ECAL1 src id 624 100 % errors
  - LOAD → no config server.
  - pccofe23 needs restart, but that requires acces...
  - postponed when there is no beam.
- Daq\_Vme\_Bms2 alarm in DSC masked, will be looked at tomorrow.

#### Watch the MTV and (be) coool!

#### Common problems

- PMMs give errors and/or have data missing
  - no errors, but missing data
    - $\rightarrow$  stop & LOAD -ra,
  - error persists several spills  $\rightarrow$  stop & LOAD -A,
  - no config server → powercycle pccofe15
  - I2C error → powercyce MM LV
  - other errors: try to take data and watch..
- DCs or othe important detectors give errors and/or have data missing
  - $\rightarrow$  stop & LOAD -A



- ECAL1 src id 624 100 % errors
  - LOAD → no config server.
    - pccofe23 needs restart, but that requires acces...
  - postponed when there is no beam.
- Daq\_Vme\_Bms2 alarm in DSC masked, will be looked at tomorrow.



#### Watch the MTV and (be) coool!

#### ommon problems:

- PMMs give errors and/or have data missing
  - no errors, but missing data
    - $\rightarrow$  stop & LOAD -ra,
  - error persists several spills → stop & LOAD -A.
  - $\bullet$  no config server  $\rightarrow$  powercycle pccofe15
  - I2C error → powercyce MM LV
  - other errors: try to take data and watch..
- DCs or othe important detectors give errors and/or have data missing
  - $\rightarrow$  stop & LOAD -A


COMPASS


- ECAL1 src id 624 100 % errors
  - LOAD  $\rightarrow$  no config server.
  - pccofe23 needs restart, but that requires acces...
  - postponed when there is no beam.
- Daq\_Vme\_Bms2 alarm in DSC masked, will be looked at tomorrow.

#### Watch the MTV and (be) coool!

#### Common problems:

- PMMs give errors and/or have data missing
  - no errors, but missing data
    → stop & LOAD -ra,
  - $\bullet$  error persists several spills  $\rightarrow$  stop & LOAD -A,
  - $\bullet$  no config server  $\to$  power cycle pccofe15,
  - I2C error → powercyce MM LV,
  - other errors: try to take data and watch...
- DCs or othe important detectors give errors and/or have data missing
   stop & LOAD - A







- ECAL1 src id 624 100 % errors
  - LOAD  $\rightarrow$  no config server.
  - pccofe23 needs restart, but that requires acces...
  - postponed when there is no beam.
- Daq\_Vme\_Bms2 alarm in DSC masked, will be looked at tomorrow.


#### Watch the MTV and (be) coool!

#### Common problems:

- PMMs give errors and/or have data missing
  - no errors, but missing data
    → stop & LOAD -ra,
  - error persists several spills → stop & LOAD -A,
  - no config server → powercycle pccofe15,
  - I2C error → powercyce MM LV,
  - $\bullet$  other errors: try to take data and watch...
- DCs or othe important detectors give errors and/or have data missing
  - $\rightarrow$  stop & LOAD -A








### Backup: Tuesday 16:00 – Wednesday 8:00




- 22:00 MW01 srcid 480 was giving 100% errors
  - LOAD -A  $\rightarrow$  no config server!
  - pccofe18 not reachable by ping (useful: check\_daq)
  - pccofe18 powercycle in DCS, LOAD -A pccofe18 (after consulting experts)
- PMM noise: disappears after LOAD
- PA04 and MA01 noise: persistent.
- Disks alarm (false).
- 7:00 HV trip of DCs  $\rightarrow$  access, powercycled CAEN.




## Backup: Tuesday 16:00 – Wednesday 8:00



- 22:00 MW01 srcid 480 was giving 100% errors
  - LOAD -A  $\rightarrow$  no config server!
  - pccofe18 not reachable by ping (useful: check\_daq)
  - pccofe18 powercycle in DCS, LOAD -A pccofe18 (after consulting experts)
- PMM noise: disappears after LOAD
- PA04 and MA01 noise: persistent.
- Disks alarm (false).
- 7:00 HV trip of DCs  $\rightarrow$  access, powercycled CAEN.




pccore disk occupancies (%)




## Backup: Tuesday 16:00 – Wednesday 8:00




- 22:00 MW01 srcid 480 was giving 100 % errors
  - LOAD -A  $\rightarrow$  no config server!
  - pccofe18 not reachable by ping (useful: check\_daq)
  - pccofe18 powercycle in DCS, LOAD -A pccofe18 (after consulting experts)
- PMM noise: disappears after LOAD
- PA04 and MA01 noise: persistent.
- Disks alarm (false).
- 7:00 HV trip of DCs  $\rightarrow$  access, powercycled CAEN.



pccore disk occupancies (%)







- Target measure and reverse the polarisation
  - it took 3 h to remove the ice,
  - now polarising until the evening,
  - to be continued on the morning...
- Water leaks
  - in the beam tunnel BMS06 cooling water,
  - from the air-conditioning unit next to polarised target barracs.
- RichWall 2 missig ports FE cards exchanged.
- ECAL1 pccofe23 restarted.
- ECAL2 changed HV bases.
- DAQ
  - cross-point switch installed to MUX03
  - fast run start/stop procedure deployed.
- veto deadtime measurement in the night
- CEDAR
  - cooling: input/output test.
  - To be done: treshold scan (if possible...) without and with beam
- o ...

- Target measure and reverse the polarisation
  - it took 3 h to remove the ice,
  - now polarising until the evening,
  - to be continued on the morning...
- Water leaks
  - in the beam tunnel BMS06 cooling water,
  - from the air-conditioning unit next to polarised target barracs.
- RichWall 2 missig ports FE cards exchanged.
- ECAL1 pccofe23 restarted.
- ECAL2 changed HV bases.
- DAQ
  - cross-point switch installed to MUX03
  - fast run start/stop procedure deployed.
- veto deadtime measurement in the night
- CEDAR.
  - cooling: input/output test.
  - To be done: treshold scan (if possible...) without and with beam





Tunnel





AC unit next to PT barracks.

- Target measure and reverse the polarisation
  - it took 3 h to remove the ice,
  - now polarising until the evening,
  - to be continued on the morning...
- Water leaks
  - in the beam tunnel BMS06 cooling water.
  - from the air-conditioning unit next to polarised target barracs.
- RichWall 2 missig ports FE cards exchanged.
- ECAL1 pccofe23 restarted.
- ECAL2 changed HV bases.
- DAQ
  - cross-point switch installed to MUX03.
  - fast run start/stop procedure deployed.
- veto deadtime measurement in the night
- CEDAR.





Tunnel





AC unit next to PT barracks.

#### • Target – measure and reverse the polarisation

- it took 3 h to remove the ice,
- now polarising until the evening,
- to be continued on the morning...

#### Water leaks

- in the beam tunnel BMS06 cooling water,
- from the air-conditioning unit next to polarised target barracs.
- RichWall 2 missig ports FE cards exchanged.
- ECAL1 pccofe23 restarted.
- ECAL2 changed HV bases.
- DAQ
  - cross-point switch installed to MUX03,
  - fast run start/stop procedure deployed.
- veto deadtime measurement in the night
- CEDAR.
  - cooling: input/output test.
  - To be done: treshold scan (if possible...) without and with beam.

• ...



Tunnel






AC unit next to PT barracks.

## Backup: Wednesday 16:00 – Thursday 16:00

- Target measure and reverse the polarisation
  - Polarising 11:30–21:30, continued 8:45–...
  - We have +71% and -63% now.
- Water leaks
- •
- 23:00-01:30 Veto tests
  - deadtime measurement at different beam intensities,
  - run with no veto applied to OT and MT.
- CEDAR FE not ready, threshod scan not taken.
- Night

PA02V1 2 ports missing in coool, later only 1.

- Day
  - no beam 8:00-11:00, but we are polarising..
  - SciFi and scaler 100 % errors, LOAD didn't help, they are at pccofe15 → powercycled and solved.
    - 11:00 alignment runs
- Evening: Trigger test runs with low intensity beam (1361 spills) while polarising



## Backup: Wednesday 16:00 – Thursday 16:00

- Target measure and reverse the polarisation
  - Polarising 11:30–21:30, continued 8:45–...
  - We have +71% and -63% now.
- Water leaks
- 23:00-01:30 Veto tests
  - deadtime measurement at different beam intensities,
  - run with no veto applied to OT and MT.
- CEDAR FE not ready, threshod scan not taken.
- Night: PA02V1 2 ports missing in coool, later only 1.
- Day:
  - no beam 8:00-11:00, but we are polarising...
  - SciFi and scaler 100 % errors, LOAD didn't help, they are at pccofe15 → powercycled and solved.
    - $\bullet$  11:00 alignment runs
- Evening: Trigger test runs with low intensity beam (1361 spills) while polarising

