

Dry-Run 2020

Weekly report (23 Nov. - 27. Nov)

Carlos Azevedo

University of Aveiro



Friday (20 Nov.)

- Trigger matrices changed to hodoscope mode
 - Please follow comments #63081 and 63082
- LV on in BMS stations 1-4
 - No HV due to network problem with BMS barrack
- LV/cooling and HV on for Scifi1,3 and 4
 - Some problems detected (HV cables not connect and some stations not showing data in cool)
 - Thanks to Moritz and Stefano who followed Rainer Joosten instructions
- GEMs with new pedestals
 - 737 738 739 740 750

Weekend (Saturday 21)

- Igor Koronov asked for work in DAQ during weekend
- Losses of communication with power switches (GEM, PMM LV, DC04 LV)
- New safe stop for DAQ implemented:
 - Comment #63084

Monday (23 Nov.)

- Network connectivity with GEM PS is back
- TCS signal problem [Old TCS module giving less signal].
- DAQ team also reported slow connection in X2Go server due to high number of users attached.
- NMR test [supposed in morning] will be performed in the afternoon according to EP-DT availabilities. Magnet field rotation tests tomorrow
- Alarm for the new gas flow compressor is set to on in DCS.
 - need monitoring.
 - very critical if alarm state.
 - Shift crew need to call Oleg Denisov on 169025.
 - Christophe proposed to put this number in the notification list for the alarm for non shift periods.
- Threshold scans for MMs and thresholds lowered
- RICH APV mapping check activities with Pedestal runs

Tuesday (24 Nov.)

- Problem with scaler readout
 - Time out over night. Now fixed
- Network connection lost:
 - Brain boxes PCCOBB01, PCCOBB02, and PCCOBB03 have been power-cycled.
- Measurement of TCS between trigger and DAQ barracks.
 - Signal loss measured
- Scifi1 and Scifi4 went off during night
 - No reason was identified. Investigation on course
- Network to BMS barrack reestablished
 - Inclusion of BMS HV in DCS
- PT communication test between NMR and magnets
 - Tested the safety region. Magnet commission almost ready

Wednesday (25 Nov.)

- DAQ crashed overnight. Started shift with a CleanDaq procedure
- MWPC srID 460 with errors since yesterday. Was removed from DAQ in order to take pedestals for DC5 (same multiplexer)
- PMM 380, 381 LV went off and run was stopped
 - Switched ON and loaded. 380 giving errors but running
- DAQ safety stop was not working properly
 - If connection lost with TCS a DAQ crash occurs in 2-3 min.
 - Procedure changed to crash immediately as the signal is lost and notifies the shifters
- HCAI1 606-609 were activated in FEDB.
 - 608 and 609 are working fine.
 - Front-ends attached to 606 and 607 are not powered on

(CONTINUE IN NEXT SLIDE)

Wednesday (25 Nov.)

- PT magnet commissioning
 - Changing the field from dipole to solenoid and vice-versa
 - Magnet current off during this week
- RICH PAPMT threshold scans

Thursday (26 Nov.)

- DAQ still crashing due to the signal loss with TCS
- Integration of several temperature sensors and HV for RICH MWPCs in DCS
- PT: starting to setup the microwave generator
- RICH: integration of LED pulser in DAQ