

English

# OX 2000 / TX 2000 OX 2000+ / TX 2000+

## OXYGENOMETER AND TOXIMETER



## USE AND MAINTENANCE

**OLDHAM**  
Group



CE  
Fabrication  
française

Réf.: CD00001

Code: 03 MT TX2000/TX2000+ GB05

# OLDHAM SA

## GAS AND FLAME DETECTION

## DUST EMISSION ANALYSIS

We thank you for choosing an **OLDHAM SA** instrument.

We have taken every step to ensure that this equipment continues to give you complete satisfaction.

Please read the instruction manual carefully before using the instrument.



## LIMITS OF RESPONSIBILITY

- \* **OLDHAM SA** hereby rejects any and all responsibility with regard to any person for material damage, bodily injury or death resulting in whole or in part from the inappropriate use, installation or storage of its equipment not conforming to the instructions and to warnings and/or not conforming to standards and regulations in force.
- \* **OLDHAM SA** does not allow or authorize any company, person or legal entity to assume such responsibility on the part of **OLDHAM SA**, even if involved in the sale of the products of **OLDHAM SA**.
- \* **OLDHAM SA** shall not be liable for any direct or indirect damage, or any direct or indirect legally awarded damages resulting from the sale and use of any of its products, **UNLESS THOSE PRODUCTS WERE SPECIFIED AND CHOSEN BY OLDHAM SA FOR THE USE MADE OF THEM.**

## OWNERSHIP CLAUSES


- \* Sketches, drawings, specifications and data included herein contain confidential information which is the property of **OLDHAM SA**.
- \* These information shall not be, in part or in whole, physically, electronically or in any other form whatsoever, reproduced, copied, divulged, translated, used as a basis for the manufacture or sale of **OLDHAM SA** equipment or used for any other reason **without the prior approval of OLDHAM SA.**

## WARNINGS

- \* This document is not a contractually binding document, **OLDHAM SA** reserves the right to make any changes, without notice, to the technical characteristics of its equipment in order to improve performance levels, in the interest of its customers.
- \* **CAREFULLY READ THE INSTRUCTIONS BEFORE ALL FIRST USE:**  
This instruction manual must be read by any person who is, or will be, responsible for the use, maintenance or repair of this equipment.
- \* This equipment will conform with the specified performance levels only if it is used, maintained and repaired in accordance with the directives of **OLDHAM SA** and by **OLDHAM SA** personnel or personnel authorized by **OLDHAM SA**.




**FIGURE 1**  
**General view**




<b>1</b>	Protective filter for module
<b>2</b>	clip
<b>3</b>	Protective cover for module
<b>4</b>	Back lighted liquid cristal display
<b>5</b>	Colour ring mentionning type of module
<b>6</b>	Visual indicator
<b>7</b>	Buzzer (audible alarm)
<b>8</b>	Mini and maxi detected at the last utilisation Current batteries voltage
<b>9</b>	Tactile keys

**FIGURE 2**  
**Inside view**



**FIGURE 3**  
**TX2000 (+) "HBCO" Version**



<b>1</b>	Te shape sampling device (plastic)
<b>2</b>	Interchangeable tip (pasteboard)
<b>3</b>	<b>CELL CAP (NOZZLE) SPECIFIC TO COHB</b>
<b>4</b>	TX 2000 (+) "CO"

# TABLE OF CONTENTS

<b>I.</b>	<b>PRESENTATION.....</b>	<b>9</b>
1.	<b>POWER SUPPLY - OX/TX2000 VERSION .....</b>	<b>9</b>
1.1.	Fitting or replacement of dry batteries:.....	10
2.	<b>POWER SUPPLY – OX/TX2000+ VERSION .....</b>	<b>10</b>
2.1.	Replacement of dry batteries .....	10
2.2.	Reinitialization of the dry batteries "controller" .....	11
3.	<b>MEASUREMENT SENSOR (toxic or oxygen) .....</b>	<b>11</b>
3.1.	Presentation.....	11
3.2.	Fitting or replacement .....	11
4.	<b>CARRIAGE OF THE TX2000(+) / OX 2000(+) .....</b>	<b>12</b>
<b>II.</b>	<b>USE.....</b>	<b>12</b>
1.	<b>OPERATING THE INSTRUMENT .....</b>	<b>12</b>
2.	<b>DATA GIVEN BY THE DISPLAY .....</b>	<b>13</b>
3.	<b>SWITCHING ON.....</b>	<b>13</b>
4.	<b>SWITCHING OFF.....</b>	<b>14</b>
5.	<b>ILLUMINATION.....</b>	<b>15</b>
6.	<b>SCROLLING THE PARAMETERS .....</b>	<b>15</b>
6.1.	Manual acknowledgment of «MINI » et «MAXI » .....	16
7.	<b>THE ALARMS.....</b>	<b>17</b>
8.	<b>CLEARING THE ALARMS.....</b>	<b>20</b>
<b>III.</b>	<b>MAINTENANCE AND SERVICING.....</b>	<b>21</b>
1.	<b>MAINTENANCE .....</b>	<b>21</b>
2.	<b>PROGRAMMING .....</b>	<b>22</b>
3.	<b>CALIBRATION .....</b>	<b>23</b>
3.1.	Calibration procedure .....	23
3.2.	Adjusting the zero in clean air (only for toximeter version).....	23
3.3.	Adjusting the sensitivity.....	24
4.	<b>SENSOR REPLACEMENT.....</b>	<b>26</b>
<b>IV.</b>	<b>ACCESSORIES.....</b>	<b>26</b>
<b>V.</b>	<b>SPARE PARTS LIST.....</b>	<b>27</b>
<b>VI.</b>	<b>LIST OF THE DIFFERENTS SENSORS .....</b>	<b>28</b>
<b>VII.</b>	<b>TECHNICAL DATA.....</b>	<b>29</b>
1.	<b>GAS DETECTOR .....</b>	<b>29</b>
2.	<b>SENSORS.....</b>	<b>32</b>
2.1.	Interferents : .....	33
<b>VIII.</b>	<b>"HBCO" VERSION .....</b>	<b>34</b>
1.	<b>With direct reading in "ppm CO" or "% COHB".....</b>	<b>34</b>
2.	<b>Preparation of the patient .....</b>	<b>34</b>

## I. PRESENTATION.

---

See figure 1 at the beginning of this manual

**T**he TX/OX2000(+) is a stand-alone, “pocket ” oxygenometer or toximeter intended for the (continuous) detection of toxic or oxygen gases or vapours.

The TX/OX2000(+) is equipped with a plug-in sensor which can be accessed after unscrewing the sensor cap on the top of the instrument.

The TX/OX2000(+) displays the gas concentrations on a liquid crystal display fitted with an illumination device. A special version also exists not to display the measurement but the messages **GO** or **GAS**.

In the event of an alarm or anomalies the instrument activates an audible and visible alarm.

An periodic audible "BEEP" (factory-programmed intervals : 120 seconds by default) shows that the instrument is working properly or indicates that the TX2000(+) has been switched off deliberately. This “beep ” can be disabled during the initialization of this device by the manufacturer.

### 1. POWER SUPPLY - OX/TX2000 VERSION

---

It is provided by :

<b>3 ALKALINE DRY BATTERIES 1,5 V</b>
<i>DURACELL MN9100</i>
<i>ENERGIZER (LRI) E90 ALKALINE</i>
<i>PANASONIC (LRI) AM5EU ALKALINE</i>
Battery life = 1300 hours

Dry or rechargeable batteries are not :

- delivered with the instrument
- interchangeable in hazardous area

**IMPORTANT**: The instrument is certified for use in group I and II explosive atmospheres and only, when it is equipped with dry batteries of a type recommended by the manufacturer.



## 1.1. Fitting or replacement of dry batteries:

➤ See figure 2 at the beginning of this manual

- Remove the rear protective caps of the TX/OX 2000 after having the four screws undone (rep 1)
- Fit the dry batteries into the compartment thought for this purpose (rep 2). Make sure that the polarity is correct as indicated on the label of the dry batteries box.
- Screw the rear caps.

## 2. POWER SUPPLY – OX/TX2000+ VERSION

---


It is provided by :

- A pack of 3V6 lithium dry batteries which gives it an autonomy while 1 year.
- This pack will be completely and easily removed when the dry batteries are discharged.

### 2.1. Replacement of dry batteries

➤ See figure 2 at the beginning of this manual

When the dry batteries are discharged, a pictogram "dry battery" appears on the LCD.




Then it is necessary to replace the "dry batteries pack" :

- Switch off the TX/OX2000+
- Remove the rear protective caps of the TX/OX2000+ after having the four screws undone (rep1)
- Replace the worn dry batteries pack by a new pack
- Screw the rear caps.


## 2.2. Reinitialization of the dry batteries "controller"

- to do at every replacement of dry batteries
- TX/OX 2000+ switch off



**IMPORTANT:** The instrument is certified for use in group I and II explosive atmospheres and only, when it is equipped with the dry batteries pack of a type recommended by OLDHAM.

## 3. MEASUREMENT SENSOR (toxic or oxygen)



### 3.1. Presentation

Being a vital element of the gas detector, the sensor of the TX/OX2000(+) must be treated with care. Mechanical impacts, splashing with water etc... may impair the quality of the measurement or even, in extreme cases, destroy the sensors.

A water-repellent and anti-dust filter protects the "head" of the sensor.

Each sensor of type electrochemical can detect one toxic or oxygen gas (see chapter VI : List of differents sensors).

### 3.2. Fitting or replacement

The sensor (fig1-rep1) can be plugged in and is accessible once the rear and the protective caps have been slightly unscrewed (fig.1.-rep3).

**IMPORTANT :** This work is reserved for authorized and qualified personnel since it could possibly jeopardize the safety of detection.

## 4. CARRIAGE OF THE TX2000(+) / OX 2000(+)

- Clip (fig 1.rep2)

The user can get on with his work while leaving the instrument to monitor the surrounding atmosphere: the TX/OX2000(+) is attached to his clothing using the clip provided for the purpose

**Attention :** in order to be able to take readings correctly, the sensor should never be obstructed.

## II. USE

### 1. OPERATING THE INSTRUMENT

This is done using the touch areas located on the front panel of the TX/OX2000(+) (fig1. rep9).

- Switching the instrument on or off
- Enter



- Illuminating the liquid crystal display
- Scrolling the parameters and menus
- “down ” key



- Clearance of the gas alarm
- “ up ” key
- "yes" or "no" for confirmation.



- use of the programming and calibration menus
- Reinitialization of the dry batteries "controller"



and



**Comment:** an interval<sup>1</sup> of 3 minutes minimum and 7 minutes maximum is allowed between two depressions of the keys, otherwise the instrument will "restart" in "normal" mode

<sup>1</sup> Configuration of the interval depends on detected gas

## 2. DATA GIVEN BY THE DISPLAY (fig1-rep4)

---

The liquid Crystal **display** allows messages to be read clearly:

- **3 digits 1/2** for displaying the measurement
- Equipped with back light by light-emitting diodes.
- **4 pictograms** supplementing the audible and visual alarms relating to the exceeding of thresholds, battery faults, maintenance mode.


## 3. SWITCHING ON

---

The TX/OX2000(+) is switched on by pressing momentarily on the following key 

A regular audible “ beep ” signals that the instrument is operating correctly.  
The interval between the "beeps" is factory-programmable, and the "beeps" can be disabled.

The following appear in succession on the display, accompanied by a continuous visual and audible signal of 4 seconds :



Test display

**r 1.6**

Software version used

0


Year of manufacturing

004


Day of manufacturing, in the year

001

Serial number

 1 ---

Display of 1<sup>st</sup> adjustable alarm threshold in toxic gas, or of « low » adjustable gas threshold in oxygen..

 2 ---

Display of 2<sup>nd</sup> fixed alarm threshold in toxic gas, or of « high » adjustable gas threshold in oxygen..

Display of the alarm threshold STEL (15 mn) fixed  
Display of the alarm threshold TWA (8 hours) fixed


M8H	"Average on 8 hours" (TWA)
5	Alarm threshold on 8 hours
M15	Average on 15 mn (STEL)
IO	Alarm threshold on 15 mn
tSt	Display of test period (stabilisation) (alternatively "tst" and remaining time).
000	Display of measurement or <span style="border: 1px solid black; padding: 2px 10px;">go</span> (depends on version), after stabilisation time.
bon	

**Note :**

The instrument is initialised to detect only **one type of gas (toxic or oxygen)**.  
The "detected" gas is programmed in the factory and engraved on a label [sticked on TX/OX2000(+) housing].

#### 4. SWITCHING OFF<sup>1</sup>

---



Keep the "OFF" key pressed  
The display then indicates the following countdown:

- 2-
- 1-
- 0-

and goes out (with confirmation beep).  
Then release the key.

---

<sup>1</sup> We can remove only in factory the « OFF » function if you need (special version).  
All parameter existing when the instrument operates will be when dry batteries are replacing

## 5. ILLUMINATION

---

In order to read the measurement in dark locations it is possible to illuminate the display by momentarily pressing the following key :



2 red light-emitting diodes placed on either side of the display provide this illumination for 10 seconds (as standard).

## 6. SCROLLING THE PARAMETERS

---

By pressing momentarily and successively on the following key



In first press on key, display is back-lighed then :

**LO**

The lowest measurement detected since the instrument was switched on (refreshed each time the instrument is switched back on)

**TM**

Cyclic display of measurement if no new depression appears



**HI**

The highest measurement detected since the instrument was switched on (refreshed each time the instrument is switched back on)

**TM**

Cyclic display of measurement if no new depression appears

**NB** : these measurement displays **LO** and **HI** do not be available in « detector » special version **go** or **GAS**



**M15**

Averaged alarm on 15 mn : STEL

**100**

"STEL" current value permanently<sup>1</sup> calculated (sample)

---

<sup>1</sup> This value is put back to zero at every start of the device.



**M8H**

Averaged alarm on 8 hours : TWA

**10**

"TWA" current value permanently calculated



**bAt**

Test of dry batteries

IIII

Segments indicating dry batteries or batteries operating  
(the number of segments depends on remaining of autonomy)

Cyclic display






**TM**

Return to display of the current measurement in ppm of the toxic measurement detected or in % oxygen

### 6.1. Manual acknowledgment of « MINI » et « MAXI »

It is possible to reinitialize (up-date) manually in normal operating (measurement display) the lowest measurement **LO** and the highest measurement **HI** :

- press simultaneously on the 2 following keys  and 



- release the keys...

## 7. THE ALARMS

---

### Visual:

Red indicator clearly visible on 4 sides and located at the top of the instrument (see figure 1 rep 6).




### Audible:

Loud buzzer located above the front panel of the instrument (see figure 1 rep.7).



### GAS:

The “ gas ” audible and visual alarm is triggered when at least one of the two preprogrammed thresholds is exceeded (instantaneous or STEL/TWA for the taximeter version)

#### \* Toximeter version<sup>1</sup> :

- **The instantaneous adjustable threshold**<sup>2</sup>: can be altered as desired by the user with the help of the maintenance / programming mode, and identified by the following pictogram  **1**
- **The instantaneous fixed threshold**<sup>3</sup>: programmed by OLDHAM. It is identified by the following pictogram  **2**
- **The STEL threshold**<sup>3</sup> : Programmed by OLDHAM. Display of M15 alternatively with the value
- **The TWA threshold**<sup>3</sup> : Programmed by OLDHAM. Display of M8H alternatively with the value.
- **The STEL/TWA thresholds**<sup>3</sup> : The STEL and TWA thresholds are programmed by OLDHAM at the reinitialization of the device and cannot be modified by the user. The thresholds are programmed by default following the certificated values. It is identified by the pictogram  **2**

#### \* Oxygenometer version :

- **The “ down ” threshold**<sup>2</sup> : adjustable from 0% oxygen to the "up" threshold and identified by the following pictogram  **1**
- **The “ up ” threshold**<sup>2</sup> : adjustable up to 25% oxygen and identified by the following pictogram  **2**

---

<sup>1</sup> the instantaneous and STEL/TWA alarms are not available for the range 0-5 % COHB (HBCO)°

<sup>2</sup> Threshold 1 = 1 beep every 2 seconds

<sup>3</sup> Threshold 2 = 1 beep each second



## Table of " pulsed " audible and visual alarms

DISPLAY	CAUSE	REMEDY
GAS (special version)	Instantaneous or averaged threshold exceeded	Alarm can be cleared manually <sup>1</sup>
XPPM or % O <sub>2</sub> Alarm pictogram	Instantaneous or averaged threshold exceeded	Alarm can be cleared manually
Dry battery pictogram	The battery is beginning to discharge	Audible and visual alarms can be cleared Change dry batteries

### FAULTS<sup>2</sup>

The faults can be classed into 2 families:

- Those relating to the sensor (out-of-range, sensor worn out, unsuccessful calibration etc...).
- Those relating to the instrument itself : worn out dry batteries, OX / TX2000(+) fault.

Visual alarm  
(red indicator)



Audible alarm  
(buzzer)

<sup>1</sup> Notes ! In special version, you can obtain an automatic reset of alarm (without manual acknowledgment) and when measurement leaves alarm. The altering is made possible before shipment (untested by DMT).

<sup>2</sup> The various faults generates a "continuous" audible and visual alarm.

Note : If several faults are simultaneously present, the display will indicate the sum of the faults

DISPLAY	CAUSE	REMEDY
BAT pictogramme	Dry batteries are worn : the instrument is no longer usable.	- Switch off the instrument - Alarm cannot be cleared - Replace dry batteries pack
OR	Measurement range exceeded	- Alarm can be cleared manually
DEF 1 (cyclic)	Zero fault : sensor zero too much shifted to low or high	- Calibrate
DEF 2 (cyclic)	Sensitivity fault : low sensitivity	- Recalibrate and if the fault persists : the sensor must be replaced.
DEF 4 (cyclic)	Worn out sensor fault : low sensitivity	- alarm cannot be cleared : - Replace sensor and calibrate again
DEF 8 (cyclic)	Eeprom fault : eeprom memory is not initialized	- Return the instrument into factory to be reinitialised.
DEF 16 (cyclic)	Measurement too negative or sensor faulty	- Recalibrate and if the fault persists : the sensor must be replaced
ERR 35      69	Problem of communication between micro and eeprom	- Return the instrument into factory to be repaired
DEF à 64 (cyclic)	Component fault : T° detector is faulty	- Return the instrument into factory to be repaired
DEF 128 (cyclic)	Wrong type of sensor.	Alarm cannot be cleared Connect the correct type of sensor
DEF 128 (cyclic)	Sensor absent	- Alarm cannot be cleared : fit the sensor after switching off the instrument

## 8. CLEARING THE ALARMS

---

### \* Clearing the instantaneous GAS, STEL and TWA alarms:

by pressing momentarily on the following button




Clearing<sup>1</sup> the alarm involves cancelling the “ pulsed ” audible signal and turning off the alarm indicator on condition that the user has left the danger area.<sup>2</sup>

**NB :** if the audible alarm is cleared while a threshold is still exceeded : the indicator will continue to flash and the corresponding pictogram will remain "steady".  
Otherwise, the indicator will switch off when measurement is under the alarm threshold.

### \* Clearing the FAULT alarms:

In the event of a fault it is not possible to clear the “ continuous ” audible and visual alarms, except in case of over range  OR  which can be cleared.

Clearing button



---

<sup>1</sup> An option allows to automatically regenerate the buzzer 5 minutes after the acknowledgement if the alarm is still on.

<sup>2</sup> An option makes possible the automatic acknowledgement of alarms : the alarms automatically acknowledge as soon as the value gets under the threshold. If this option is requested, the manual acknowledgement is no longer possible (also the « OVER RANGE ») (untested by DMT).

### III. MAINTENANCE AND SERVICING

#### Important

Being a safety instrument , it is necessary to calibrate the TX2000(+) or OX 2000(+) at least **once a year following use**


This work is reserved for authorized and qualified personnel since it could possibly jeopardize the safety of detection.

#### 1. MAINTENANCE

A maintenance program, integrated to the instrument allows to modify easily alarm threshold (s) (programming) and to proceed with prevent calibrations or further to the change of a cell.

##### Use of the program:

The instrument being under normal operation, press simultaneously, and this during 5 seconds at least, on the following keys:



## 2. PROGRAMMING

---

The "programming" menu allows manual programming of the adjustable alarm threshold: threshold 1 for toxic version [TX2000(+)], or up or down thresholds in oxygen version [OX 2000(+)].

Programming example in toximeter version :

PrG


Display the "**PROGRAMMING**" menu



Enter the programming menu

40

Display the current alarm threshold



Alter the alarm threshold



Enter the new threshold

CnF

Display "request for confirmation"



nO

Display confirmation : NO



Display "yes or no" of confirmation  
(with each depression of the button)

Yes

Display confirmation: YES



Enter the confirmation chosen<sup>1</sup>

š

Return to the normal display of the current measurement

---

<sup>1</sup> In order to keep old programming, confirmation "NO" cancels every changes

### 3. CALIBRATION

---

The only means of checking that the instrument's detection function is working properly is the **calibration** performed with the help of a **standard gas**.

Calibration must be done :

- At least once a year following the use and the type of sensor
- whenever the instrument has been exposed to overly high concentrations of gas
- when an instrument has been stored for more than one month and without use
- when changing of sensors
- when fault appears

Within the calibration the menu "visible and audible" alarms are not triggered.

#### 3.1. Calibration procedure

“ Calibration ” menu consists of

- setting the zero in clean air and the sensitivity with calibration gas in TX2000(+) version (toxic gases).
- Adjust oxygen sensitivity in OX 2000(+) version.

#### 3.2. Adjusting the zero in clean air (only for toximeter version)



Display the “ programming ” menu



To display the "calibration" menu



Display the "calibration" menu



ENTER

To enter the “ calibration ” menu



Zero adjustment



To enter the zero adjustment procedure



Display the current value "zero".



To adjust value “ zero ” if necessary  
(in reality, 1 pression on "+" or "-" put the value to "0")



to enter the zero adjustment

### 3.3. Adjusting the sensitivity [TX2000(+) and OX 2000(+)] :

- Position the gas inlet pipe level with the sensor
- Connect up the hose from the calibration kit and inject the standard gas (>30% range of the gas detected otherwise only the zero will be confirmed [auto-zero] for toxic version), maintaining a flow rate of 30 l/h.
- In oxygenometer version, this adjustment can be done without gas but be sure to be in clean air.

Then continue scrolling the calibration menu:




Display the adjustment of sensitivity



To enter the sensitivity adjustment procedure



Display the measurement corresponding almost to the value of standard gas :  
**Wait for the signal to stabilize.**



To adjust calibration gas correct value



To enter the adjustment of sensitivity



Display confirmation of sensibility requested



Acceptance of request for confirmation



Display the confirmation: NO



Display of "YES or NO" for confirmation  
(with each depression of the button)



Display the confirmation: YES



Enter the chosen confirmation

**NO:** The measurements are not entered

**YES:** The measurements are entered



Return to normal display of current measurement

Note: When the calibration procedure has been completed, do not forget to remove the calibration cap from instrument.



## 4. SENSOR REPLACEMENT

---

Necessary when :

- Calibration not to be done (low sensibility) so sensor is worn out (DEF4).
- Wrong type of sensor connection (DEF128), for example (see table of faults).

**IMPORTANT :** This work is reserved for authorized and qualified personnel since it could possibly jeopardize the safety of detection.

## IV. ACCESSORIES

---

DESIGNATION	RERERENCES
Calibration kit (cap + hose) without gas	6 331 135
Screw driver	6 145 848
Leather carrying case for OX/TX2000	6.121.571
Leather carrying case for OX/TX2000+	6.121.588
Anti-condensation filter	6.335.966
Active carbon filter	6.335.814

## V. SPARE PARTS LIST

---

DESIGNATION	PART NUMBER
Clip	6 142 251
Seal for sensor cover	6 136 039
Oxygen sensor filter	6 335 957
Standard toxic sensor filter (Teflon)	6 335 956
Chlorine sensor filter for CL <sub>2</sub> , HCL and HCN	6 335 956
FHC screw M 2,5x12	6 902 505
Seal for sensor TX2000	6.136.030
Lithium dry batteries pack (OX/TX2000+)	6 111 214
Sensor cover for TX2000+	6.123.562 <sup>1</sup>
Sensor cover for OX 2000+	6.123.566
LR01 dry batteries	6.111.204
OX/TX2000 housing	6.121.549

### **WARNING :**

**Only use guaranteed original OLDHAM spare parts ; the safety of the equipment could be jeopardized if you use any other parts.**

**The device is intrinsically safe, substitution of components may impair intrinsic safety.**

---

<sup>1</sup> For users which have the oldest version of OX/TX2000 (i.e. before May 2000), we have created two updating kits (new version releasing of the cell cap).

TX2000 kit : 6 323 616

OX2000 kit : 6 323 617

## VI. LIST OF THE DIFFERENTS SENSORS

---

Gas	Range	Part Number	Color Ring
CO	500 ppm	6 313 615	GREEN
CO	300 ppm	6 313 615	GREEN
CO ou HBCO	2000 ppm 50%	6 313 672	GREEN
H2S	100 ppm	6 313 616	BLUE (ral 5015)
NO	100 ppm	6 313 617	RED
NO2	30 ppm	6 313 618	ROUGE CLAIR
NH3	100 ppm	6 313 619	BROWN
CL2	10 ppm	6 313 620	YELLOW
Oxygen	30 %	6 313 630	WHITE
HCL	30 ppm	6 313 641	PURPLE
HCN	30 ppm	6 313 642	BLUE (ral 5002)
NH3	1000 ppm	6 313 643	BROWN
O3	1 ppm	6 313 673	GREY
H2	2000 ppm	6 313 674	PINK

## VII. TECHNICAL DATA

---

### 1. GAS DETECTOR

---

<b>Manufacturer</b>	:	OLDHAM ARRAS (France)
<b>Function</b>	:	Gas detector
<b>Type</b>	:	TX2000(+) or OX 2000(+)
<b>Gas detected</b>	:	toxic or oxygen gas or vapours
<b>Measurement</b>	:	continuous
<b>Mode</b>	:	Clear display on content (% or ppm)
<b>Sensor</b>	:	can be unplugged for maintenance
<b>Display</b>	:	liquid crystal
<b>Screen</b>	:	illuminated momentarily on request
<b>Sensor fault</b>	:	visual and audible “ continuous ” alarm
<b>Battery fault</b>	:	audible, visual and “ continuous ” alarm + pictogram

#### Checking of correct operation :

- Intermittent luminous and audible signals (adjustable intervals)
- Self-test when switching on

#### Indications :

- An alarm indicator
- Pictograms

#### Alarms :

##### ⇒ Toximeter version

- An adjustable instantaneous threshold
- An fixed instantaneous threshold (preset in the factory)
- 2 averaged thresholds : STEL en TWA (preset in the factory)

##### ⇒ Oxygen version

- An adjustable up threshold
- An adjustable down threshold

**Audible alarm** : buzzer, 80db at 30 cm

**Power supply :**

- 1 lithium dry batteries pack : autonomy maxi : 7000 hours
- 3 LR01 dry batteries : averaged autonomy : 1500 hours

**Miscellaneous :**

- Keypad control with 3 buttons
- Maintenance menu

**Waterproofing** : IP 66

**Casing** : antistatic polycarbonate

**Weight** : about 95 gr.

**Operating temperature** : -10°C to +40°C

**Dimensions** : 87 x 60 x 30 mm (OX/TX2000+ Version)  
87 x 60 x 25 mm (OX/TX2000 Version)

**Certification :** “ Industrial ”  $\Sigma X$   
EEx i a IIC T4  
INERIS 98.E 5087X

“ Mining ”  $\Sigma X$   
EEx ia I  
INERIS 98.D 7019X

**CENELEC standards** EN 50014 A1 to A5  
EN 50018 A1 to A3  
EN 50020 A1 to A5

The performing tests in OX2000 oxygenometer version have been made by DMT :  
n°PFG – Nr -41300301

CSA N° LR 104516-6



La Société **OLDHAM S.A.**, ZI Est 62000 Arras France, atteste que le matériel neuf destiné à être utilisé en Atmosphères Explosives désigné ci-après:  
( *The Company OLDHAM S.A.*, ZI Est 62000 Arras France, declares that the following new material intended for use in Explosive Atmospheres:)

**Détecteurs de gaz ( Gas detectors) TX2000, TX2000+, OX2000, OX2000+**

sont conformes aux exigences des Directives Européennes suivantes :  
(*comply with the requirements of the following European Directive :*)

**I) DIRECTIVE EUROPEENNE 94/9/CE du 23 mars 1994**  
**relative aux Atmosphères Explosives**  
*The European Directive 94/9/CE of 23 march 1994*  
*Concerning the Explosive Atmospheres*

Normes harmonisées appliquées :  
(*Harmonised applied Standards*)

EN 50014 de Juin 1997 + amendements 1 et 2  
EN 50020 de Août 1994  
EN 50284 de Janvier 1999  
EN 50303 de juillet 2000  
EN 50104 de juillet 1999

N° de l'Attestation CE de type du matériel :  
(*N° of EC type examination certificate*)

INERIS 02ATEX0050

N° de la Notification Assurance Qualité de  
Production de l'usine de fabrication de Arras :  
(*N° of the Production Quality Assurance*  
*Notification of the Arras factory*)

INERIS 00ATEXQ403

Délivrés par l' Organisme notifié sous le numéro 0080: INERIS, rue Taffanel, 60550 Verneuil  
(*Issued by the Notified Body n°0080*) en Halatte, France.

**II) DIRECTIVE EUROPEENNE 89/336/CEE du 3 mai 1989**  
**relative à la Compatibilité Electromagnétique**  
*The European Directive 89/336/CEE of 3 may 1989*  
*Concerning the ELECTROMAGNETIC COMPATIBILITY*

Normes harmonisées appliquées :  
(*Harmonised applied Standards*)

EN 50270

Essais effectués par ( *Tests issued by*):

LCIE 92260 Fontenay aux Roses France  
Mines de Douai 59508 Douai France

N° des rapports d'essais (*N° of tests reports*):

N° 3261 020-2 & N° CEM 2000/04

CE/ATEX103

Arras, le 31/07/02

Le Représentant de l'entreprise  
On Behalf of the firm

Lionel Witrant



Directeur Technique  
Technical Director

## 2. SENSORS

*Sensors can be unplugged for replacement*

### Data chart of different sensors

	O <sub>2</sub> ( <sup>1</sup> )	H <sub>2</sub> S	CO	CO	H <sub>2</sub>	HCN	HCL	NO	NO <sub>2</sub>	NH <sub>3</sub>	NH <sub>3</sub>	O <sub>3</sub>	CL <sub>2</sub>	Partial pressure O <sub>2</sub> (1)
<b>Standard range</b>	30 %	100 ppm	500 ppm CO or 50% HBCO	2000 ppm	2000 ppm	30 ppm	30 ppm	100 ppm	30 ppm	100 ppm	1000 ppm	1 ppm	10 ppm	20 à 300 mbars O <sub>2</sub>
<b>Accuracy in % of full scale</b>	< 0,5 % volume O <sub>2</sub>	< 5 %	< 5 %	< 5 %	< 5 %	< 5 %	< 5 %	< 5 %	< 5 %	< 5 %	< 5 %	De 0 à 0,2 ppm ⇒ ± 0,03 ppm De 0,2 à 1 ppm ⇒ ± 0,05 ppm	< 5 %	< 5 mbar O <sub>2</sub> (à 20°C)
<b>Zero drift</b>	< 2% relative per month	< 1 ppm / 6 months	< 10 ppm / 6 months	< 20 ppm / 6 months	< 50 ppm / 6 months	< 0,5 ppm / 6 months	< 1 ppm / 6 months	< 2 ppm / 6 months	< 1 ppm / 6 months	< 3 ppm / 6 months	< 15 ppm / 6 months	< 0,05 ppm / 6 months	< 0,5 ppm / 6 months	
<b>Response time</b>	< 15 s	< 30 s	< 40 s	< 40 s	< 150 s	< 90 s	< 120 s	< 30 s	< 100 s	< 220 s	< 5 mn	< 120 s	< 180 s	< 15 s
<b>Lifetime</b>	> 12 months	24 months	24 months	24 months	24 months	18 months	24 months	> 12 months	> 12 months	> 12 months	12 months	12 months	> 12 months	> 16 mois
<b>Warranty</b>	12 mois	12 months	12 months	12 months	14 months	12 months	12 months	12 months	12 months	9 months	42 weeks	12 months	12 months	12 mois
<b>Alarm 1 factory set</b>	19 %	5 ppm	50 ppm	50 ppm	200 ppm	5 ppm	5 ppm	25 ppm	3 ppm	25 ppm	50 ppm	0,2 ppm	1 ppm	19 %
<b>Alarm 2 factory set</b>	23 %	10 ppm	100 ppm	100 ppm	1000 ppm	10 ppm	10 ppm	50 ppm	5 ppm	50 ppm	150 ppm	0,5 ppm	2,5 ppm	23 %

<sup>1</sup> Oxygen sensors : Range of pressure in use = atmospherical pressure ±10%  
Range of humidity in use = from 10 to 60 % of humidity  
Temperature of storage = from 4 to 12 °C

## 2.1. Interferents :

	<b>Interferences</b>	<b>Reading</b>
<b>TX2000(+) CO 500 ppm</b>	H <sub>2</sub> 1000 p p m H <sub>2</sub> S 30 ppm HCN 30 ppm NH <sub>3</sub> 100 ppm NO 49 ppm SO <sub>2</sub> 11 ppm NO <sub>2</sub> 30 ppm C <sub>2</sub> H <sub>4</sub> 100 ppm	450 0 0 0 7 0 0 75
<b>TX2000(+) CO 2000 ppm</b>	H <sub>2</sub> 1000 p p m H <sub>2</sub> S 30 ppm HCN 30 ppm NH <sub>3</sub> 100 ppm NO 49 ppm SO <sub>2</sub> 11 ppm NO <sub>2</sub> 30 ppm C <sub>2</sub> H <sub>4</sub> 100 ppm	450 0 0 0 7 0 0 75
<b>TX2000(+) H<sub>2</sub>S 30.0 not interferent to unsaturated</b>	H <sub>2</sub> 1000 p p m CO 300 ppm C <sub>2</sub> H <sub>2</sub> 300 ppm NH <sub>3</sub> 100 ppm	0 0 0 0
<b>TX2000(+) H<sub>2</sub>S 100</b>	H <sub>2</sub> 1000 p p m CO 300 ppm NH <sub>3</sub> 110 ppm NO 49 ppm SO <sub>2</sub> 11 ppm NO <sub>2</sub> 10 ppm C <sub>2</sub> H <sub>4</sub> 100 ppm	15 18 0 2 4 0 3
<b>TX2000(+) NH<sub>3</sub> 100</b>	H <sub>2</sub> S 25 p p m CO 100 ppm SO <sub>2</sub> 25 ppm C <sub>2</sub> H <sub>4</sub> 100 ppm NO 49 ppm	31 76 -21 0 -3
<b>TX2000(+) NH<sub>3</sub> 1000</b>	Cl <sub>2</sub> 9 p p m H <sub>2</sub> S 29 ppm CO 300 ppm SO <sub>2</sub> 10 ppm H <sub>2</sub> 1000 ppm	-6 80 300 12 25
<b>TX2000(+) NO 100</b>	H <sub>2</sub> S 30 p p m CO 300 ppm SO <sub>2</sub> 29 ppm C <sub>2</sub> H <sub>4</sub> 100 ppm	21 0 0 0
<b>TX2000(+) NO<sub>2</sub> 30.0</b>	H <sub>2</sub> S 30 p p m CO 100 ppm SO <sub>2</sub> 11 ppm C <sub>2</sub> H <sub>4</sub> 100 ppm Cl <sub>2</sub> 1 ppm O <sub>3</sub> 1 ppm NO 49 ppm	47 102 20 0 1.5 to 3 ppm 0.7 -3
<b>TX2000(+) Cl<sub>2</sub> 10.0</b>	H <sub>2</sub> S 30 p p m CO 100 ppm SO <sub>2</sub> 11 ppm C <sub>2</sub> H <sub>4</sub> 100 ppm O <sub>3</sub> 0.6 ppm NO 49 ppm	Yes undetermined coeff. Yes undetermined coeff. Yes undetermined coeff. No 0.1 ppm Yes undetermined coeff.



TX2000(+) HCl 30.0	Cl <sub>2</sub> 10 ppm	0
	SO <sub>2</sub> 10 ppm	2
	H <sub>2</sub> S 25 ppm	58
	NO 50 ppm	14
	NH <sub>3</sub> 100 ppm	0
	H <sub>2</sub> 1000 ppm	0
	CO 100 ppm	0
	Ethanol 100 ppm	0
TX2000(+) HCN 30.0	NO <sub>2</sub> 10 ppm	-3.7
	Cl <sub>2</sub> 10 ppm	-1.5
	SO <sub>2</sub> 30 ppm	4.6
	H <sub>2</sub> S 10 ppm	27
	NO 50 ppm	0.5
	NH <sub>3</sub> 100 ppm	0
	H <sub>2</sub> 1000 ppm	0.1
	CO 100 ppm	0.3
Ethanol 100 ppm	0	

## VIII. "HBCO" VERSION

---

### 1. With direct reading in "ppm CO" or "% COHB"

---

- You can forecast when purchasing the use of the TX 2000 "CO" or TX2000+ "CO"
  - as TX 2000(+) "COHB" : direct reading in % COHB
  - as TX 2000(+) CO : display in ppm CO
  - or TX 2000(+) united "CO" and "COHB" : programmable display in ppm CO or % COHB.
- The user can then pass from a display to the other (ppm CO → % COHB) pressing twice on the key



**Note : For this version TX2000(+) COHB "direct reading", option "MIN/MAX" is not available and there is no alarm's releasing.**

### 2. Preparation of the patient

---

The patient is conscious, without any major breathing troubles.

After having, quickly, breathed in and out several times, the patient deeply breathes in, and then blocks his breath during 10 to 15 seconds, ...then blows, without breathing, in the interchangeable tip of the TX2000(+) COHB taking care of fully emptying his lungs.

Wait for measurement stabilisation.  
Read the indication in % COHB.

# OLDHAM s'engage - OLDHAM undertakes

Parce que la sécurité des hommes et la protection de l'environnement sont notre priorité,  
OLDHAM s'engage et définit ses normes qualité :  
Because safety for personnel and protection of the environment are our priorities,  
OLDHAM gives the following undertakings and defines its quality standards :

## 1 Les Plus

OLDHAM s'engage à travers de son personnel qualifié, à répondre rapidement et efficacement à vos besoins de conseil, de suivi de commande, et ce, partout dans le monde.  
OLDHAM s'engage à répondre dans les plus brefs délais à toutes questions d'ordre technique.

## 2 Qualité

OLDHAM s'engage à vous assurer une qualité de produits et de services à la hauteur de vos exigences, conformément au cahier des charges de la norme ISO 9001 et ATEX.

## 3 Fiabilité & Contrôles

OLDHAM s'engage à vous fournir un matériel fiable. La qualité de notre production est une condition essentielle à cette fiabilité. Elle est garantie grâce à des vérifications très strictes réalisées dès l'arrivée des matières premières, en cours et en fin de fabrication (tout matériel expédié est configuré selon vos besoins).

## 4 Mise en service

OLDHAM s'engage, si vous le désirez, à la mise en service de votre matériel par nos techniciens spécialisés. Un gage de sécurité supplémentaire.

## 5 Formation

OLDHAM s'engage à faire disposer aux utilisateurs de ses produits, d'un service de formation complet : plusieurs ingénieurs pédagogues, salle de conférences, matériels disponibles pour les manipulations, matériel informatique et de visualisation, etc.

## 6 Contrat d'entretien

OLDHAM s'engage à vous proposer des contrats d'entretien évolutifs au regard de vos besoins pour vous garantir une parfaite sécurité :

- une ou plusieurs visites par an, garantie totale ou partielle,
- renouvelable par tacite reconduction,
- incluant le réglage des centrales de mesure, l'étalonnage des appareils et le contrôle des asservissements.

## 7 Dépannage sur site

OLDHAM s'engage à faire intervenir ses techniciens du Service Après Vente rapidement. Ceci est possible grâce à la répartition judicieuse de nos agences en France et de nos agents à l'étranger.

## 8 Dépannage en usine

OLDHAM s'engage à traiter tout problème qui ne pourrait être résolu sur site par le renvoi du matériel en usine. Des équipes de techniciens spécialisés seront mobilisées pour réparer votre matériel, dans les plus brefs délais, limitant ainsi au maximum la période d'immobilisation. Pour toute intervention du Service Après Vente en France, un numéro Indigo a été mis en place : le 0 825 842 843

## 1 Strong points

Through its qualified personnel, OLDHAM undertakes to respond to your needs for advice and order follow-up services wherever in the world you may be.  
OLDHAM undertakes to answer all your technical questions as quickly as possible.

## 2 Quality

OLDHAM undertakes to provide you with products and services of a quality that meets your requirements, in accordance with the specifications of ISO 9001 and ATEX standards.

## 3 Reliability and inspections

OLDHAM undertakes to supply you with reliable equipment. The quality of our production is essential to achieve reliability. Quality is ensured by extremely strict verifications carried out as soon as raw materials are received, during production and at the end of manufacture (all shipped equipment is configured to meet your requirements).

## 4 Start-up

OLDHAM undertakes that our expert technicians will start up your equipment, if you so wish. This gives you the guarantee of additional safety.

## 5 Training

OLDHAM undertakes to provide the users of its products with a complete training service : a number of engineers specialized as instructors, conference rooms, equipment available for practical exercises, computer equipment, display equipment, etc.

## 6 Maintenance contract

OLDHAM undertakes to offer you open-ended maintenance contracts according to your needs so as to give you the guarantee of complete safety :

- one or more visits a year, comprehensive or partial warranty,
- renewal by tacit agreement,
- including the adjustment of measuring units, the calibration of equipment and the verification of servo-control systems.

## 7 Field servicing

OLDHAM undertakes to send out its After-Sales Service technicians quickly for servicing on your site. This is made possible by the efficient network of our branches throughout France and other countries.

## 8 Factory repairs

OLDHAM gives the undertaking that any problem that cannot be solved in the field will be dealt with by the return of the equipment concerned to our factory. Teams of specialized technicians are on hand to ensure the immediate repair of your equipment in the shortest possible time, so keeping downtimes for your equipment to a minimum.

For any specific technical question, please contact our After-Sales Service (M. Miguel RIESGUO) : 00 33 3 21 60 80 80

**OLDHAM**  
Group

Usine et siège social :

Z.I. Est - rue Orfila

B.P. 417 - 62 027 ARRAS Cedex FRANCE

Tél. : 03 21 60 80 80 - Fax : 03 21 60 80 00

E-mail : [information@oldham.fr](mailto:information@oldham.fr)

[www.oldham.fr](http://www.oldham.fr)

Plant and head office :

Z.I. Est - rue Orfila

B.P. 417 - 62 027 ARRAS Cedex FRANCE

Tél. : 33 3 21 60 80 80 - Fax : 33 3 21 60 80 00

E-mail : [export.department@oldham.fr](mailto:export.department@oldham.fr)

OLDHAM BELGIUM  
Belgium

☎ (33) 03 21 60 81 20  
☎ (33) 03 21 60 81 02  
[oldham.belgium@oldham.fr](mailto:oldham.belgium@oldham.fr)

OLDHAM ITALIA S.R.L.  
Italia

☎ (39) 011 38 013 71  
☎ (39) 011 38 066 13  
[paolo.pozzato@oldham.it](mailto:paolo.pozzato@oldham.it)

OLDHAM CS  
Česká Republika

☎ (42) 02627 6476  
☎ (42) 0222 728296  
[oldham@telecom.cz](mailto:oldham@telecom.cz)

OLDHAM ROMANIA  
Romania

☎ (40) 21 222 4846  
☎ (40) 21 222 5037  
[eduard.docolin@fx.ro](mailto:eduard.docolin@fx.ro)

OLDHAM CH  
Switzerland

☎ (41) 26 652 51 18  
☎ (41) 26 652 51 19  
[info@oldham.ch](mailto:info@oldham.ch)

OLDHAM GAS  
DETECTION Ltd  
UK

☎ (44) 0 1782 20 8020  
☎ (44) 0 1782 20 8228  
[sales@oldham.biz](mailto:sales@oldham.biz)

OLDHAM GmbH  
WINTER  
Deutschland

☎ (49) 231 924 10  
☎ (49) 231 924 125  
[info@winter-gaswarn.de](mailto:info@winter-gaswarn.de)