15 August 2006

MWPC shift instructions

MWPCs frontend electronics reload

In the case of:

- Some holes in the MWPCs hit profiles (booky)

- MurtpyTV errors (MWPC detector, SrcID = 448-455, 460 stays RED or ORANGE in MTV diagnostic window)

ACTION: The MWPCs readout electronics must be realoaded (reinizialized) just doing:
LOAD -A SrcID = 448-455, 460

IF DOES NOT HELP - call expert: 164874

MWPCs HV settings

In the case of HV trips, please, before put HV on be sure that beam conditions are nominal and both COMPASS spectormeter magnets are ON (apart of special alignment runs with low intensity beam).

In the case of HV setting loses, please, make an export of this settings from the most fresh MWPCs DCS settings file.

MWPC slow control account:

Username: Mwpc

Password: Privet

MWPCs gas system

In the case of any problems which coaused the persantege of CF4 changes in the gas mixture - contact the person ONCALL:

MWPCs ONCALL: 16 4874